Private

This farmhouse is a two-story, three-bay by one-bay frame building covered with wood siding. It has a wide cross gable centered at the front of the house. Windows have 2/2 pane sashes with plain trim. The entrance is located in the center bay of the front elevation.

An off center flue extends from the roof peak.

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

NAME				
HISTORIC				
	Richard L. Meador Ho	ouse		
AND/OR COMMON				
Tr. 0.0 1 57.0 1	N. Wilson Dowell, Jr	. House		
LOCATION	V	•		
STREET & NUMBER T	West Mt Harmony Road			•
CITY, TOWN			•	
	rings	VICINITY OF	CONGRESSIONAL DI	STRICT .
STATE			COUNTY	
MD			Calvert.	
CLASSIFIC	CATION			
CATEGORY	OWNERSHIP	STATUS	PR	ESENT USE
DISTRICT	PUBLIC	XOCCUPIED	AGRICULTURE	MUSEUM
Building(s)	∠ PRIVATE	UNOCCUPIED	COMMERCIAL	PARK
STRUCTURE	BOTH	WORK IN PROGRESS	EDUCATIONAL	SPRIVATE RESIDENC
SITE	PUBLIC ACQUISITION	ACCESSIBLE	ENTERTAINME	
OBJECT	IN PROCESS	YES: RESTRICTED	GOVERNMENT	SCIENTIFIC
	BEING CONSIDERED	YES UNRESTRICTED	INDUSTRIAL	_TRANSPORTATION
		X NO	MILITARY	OTHER
OWNER OF	FPROPERTY	-		
NAME	Richard L. Meador (Wilcon Down 11	m- 1)	
STREET & NUMBER	Richard L. Meador (1	v. Wilson Dowell,	ne pepnone #:	
West 1	Mt Harmony Road			
CITY, TOWN			STATE ,	zip code
Owing		VICINITY OF	MD	20736
LOCATION	OF LEGAL DESCR	IPTION	Liber #: JLB 1	0.4
COURTHOUSE.				24
REGISTRY OF DEEDS, E	Calvert County C	ourt House	Folio #: 427	
STREET & NUMBER				
CITY, TOWN	Main Street (MD	765)		
Prince Frederick			STATE	
	TATION IN EXISTI	NO CLIDADA	MD	
TITLE	IATION IN EXIST	NG SURVEYS		
DATE				
DEPOSITORY FOR		FEDERAL	STATECOUNTYLOCA	AL
SURVEY RECORDS				
CITY, TOWN			STATE	
		٠		

CONDITION

CHECK ONE ∠UNALTERED

__ALTERED

CHECK ONE

__EXCELLENT

__DETERIORATED

KORIGINAL SITE

__GOOD **≤**FAIR

__RUINS __UNEXPOSED __MOVED

DATE___

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

This farmhouse is a two-story, three bay by one bay frame building covered with wood siding. It has a wide cross-gable centered at the front of the house. Windows have 2/2 sashes with plain The entrance is located in the center bay of the fron elevation. An off-center flue extends from the roof peak. There is an ell extension to the rear and a shed roofed porch across the front.

Included in the farmstead is a frame tobacco barn and ruins of a group of sheds.

8 SIGNIFICANCE

SPECIFIC DATES		BUILDER/ARCHITECT		
1700-1799 .≰1800-1899 .≰1900-	ARTCOMMERCECOMMUNICATIONS	ENGINEERING EXPLORATION/SETTLEMENT INDUSTRY INVENTION	MUSIC PHILOSOPHY POLITICS/GOVERNMENT	THEATER TRANSPORTATION OTHER (SPECIFY)
PERIOD _PREHISTORIC 1400-1499 1500-1599 1600-1699	ARCHEOLOGY-PREHISTORIC —ARCHEOLOGY-HISTORIC —AGRICULTURE —ARCHITECTURE	REAS OF SIGNIFICANCE CH COMMUNITY PLANNING CONSERVATION ECONOMICS EDUCATION	LANDSCAPE ARCHITECTURE LAW LITERATURE MILITARY	RELIGIONSCIENCESCULPTURESOCIAL/HUMANITARIAN

This is a typical Calvert County farmhouse of no particular significance.

CONTINUE ON SEPARATE SHEET IF NECESSARY

CONTINUE ON SEPARATE SHEET IF	NECESSARY
10 GEOGRAPHICAL DATA	
ACREAGE OF NOMINATED PROPERTY	
-	
	•
•	
•	
VERBAL BOUNDARY DESCRIPTION	
•	
•	
LIST ALL STATES AND COUNTIES FOR PRO	PERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES
STATE	COUNTY
STATE	COUNTY
II FORM PREPARED BY	
NAME / TITLE	
Merry Stinson	
ORGANIZATION	DATE
STREET & NUMBER	TELEPHONE
	The state of the s
Rt 5, Box 154	STATE
Hagerstown	MD

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.


The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401

(301) 267-1438

12. chird L. Meador House

LOWER MARLBORO QUADRANGLE MARYLAND 7.5 MINUTE SERIES (TOPOGRAPHIC)





CT-329

CT-329
Richard L. Meador, Jr. House
Calvert County
Merry Stinson 4/81
S elevation